

General Environmental Incident Summary

Incident: 1920 **Notice:** 5/8/2013 1620 **Occurred:** 5/1/2013 1100

DEM Incident No:

No Further Action: ☒

Responsible Party: Brick Transport, Inc.

County: Burleigh

Twp Rng Sec Qtr: 139 79 27

Lat Long + Method: 46.83055 -100.63580 Derived from TRS

Location Description: 5 miles east of Bismarck, ND

Submitted By Info: Jerry Brick

Received By Info:

Contact Info: Jerry Brick
721 S State St
Aberdeen SD 57401

Affected Medium: 03 - soil

Near. Occupied Bldg:

Type of Incident: Tank Leak

Release Contained:

Reported to NRC: No

Contaminant: 8-20-5-4 Liquid fertilizer

Volume of Release: 963 gallons

Duration of Release: 15 minutes

Agriculture Related: Yes

**EPA Extremely
Hazardous Substance:** No

Number of Fatalities: 0

Number of Injuries: 0

Cause of Incident:

Seam on bottom of 1325 gallon plastic tank split open

Risk Evaluation:

none

Potential Env. Impacts:

none

Action Taken/Planned:

Most of spill was on highway surface. Very little of the fertilizer ended up on the grass on roadside. Driver notified our dispatch, who called for ND Highway Patrol, but did not connect with them. Driver waited approx 1 hour at the scene, but no one came. Fertilizer dried up on the roadway, so the driver delivered the remainder of his load to Bismarck.

Wastes Disposal Location:

N/A

Other Agencies Involved:

State Highway Patrol

Updates

Date: 5/8/2013 **Status:** Inspection

Author: Miller, Adam

Notes:

I viewed the spill site 5/8/2013. Minimal amount ran off roadway. Environmental impacts are unlikely. Sample collected is at lab, awaiting analysis. Spoke with owner of trucking company and explained 24-hr reporting requirement. Owner is now aware of when and how to report environmental incidents for future reference.

Updated Volume: None at the time of this update

Date: 5/9/2013 **Status:** Correspondence

Author: Roberts, Kris

Notes:

Follow-up is necessary. Adam Miller assigned. Due to late reporting, this incident may require an enforcement stance.

Updated Volume: None at the time of this update

Date: 6/15/2018 **Status:** Inspection

Author: Suess, Bill

Notes:

Visited the site and found no signs of impacts. No photos taken.

Updated Volume: None at the time of this update